


3517



Ampere	16 A
	5 .
	400 B
	6
	50-60
T	
	IP 44



Чертеж 2 MB 221	A Полоса	16		32		
		4	5	3	4	5
Размеры, мм.	a	92,5	92,5	102	102	102
	b	87	87	94	94	94
	c	84,5	84,5	94	94	94
	d	55,5	55,5	62	62	62
	e	76	76	84	84	84
	f1	5,3	5,3	5,3	5,3	5,3
	f2	5,3	5,3	5,3	5,3	5,3
	h	128	128	146	146	146
	i	21,5	21,5	26	26	26
	M	25x1,5	25x1,5	25x1,5	25x1,5	32x1,5