




225AF

| 10A | 20 |
|-------------|-------------|
| MT-225/2H□S | - |
| MT-225/3H□S | - |
| MT-225/3K□S | MT-225/3D□S |
| Винтовой | |
| 3 | |
| 690 В | |
| 690 В | |
| 6 кВ | |
| IP 20 | |
| -5~+40°C | |
| ■ | |
| ■ | |
| ■ | |
| ■ | |
| 65~240A | 65~240A |

| |
|---------|
| 65~100 |
| - |
| 85~125 |
| - |
| - |
| 100~160 |
| 120~185 |
| 160~240 |

MC-185a, 225a



400AF

| 10A | 20 |
|-------------|-------------|
| MT-400/2H□S | - |
| MT-400/3H□S | - |
| MT-400/3K□S | MT-400/3D□S |
| Винтовой | |
| 3 | |
| 690 В | |
| 690 В | |
| 6 кВ | |
| IP 20 | |
| -5~+40°C | |
| ■ | |
| ■ | |
| ■ | |
| ■ | |
| 85~400A | 85~400A |

| |
|---------|
| 85~125 |
| - |
| - |
| 100~160 |
| 120~185 |
| 160~240 |
| 200~330 |
| 260~400 |

MC-265a, 330a, 400a



800AF

| 10A | 20 |
|-------------|-------------|
| MT-800/2H□S | - |
| MT-800/3H□S | - |
| MT-800/3K□S | MT-800/3D□S |
| Винтовой | |
| 3 | |
| 690 В | |
| 690 В | |
| 6 кВ | |
| IP 20 | |
| -5~+40°C | |
| ■ | |
| ■ | |
| ■ | |
| ■ | |
| 200~800A | 200~800A |

| |
|---------|
| 200~300 |
| 260~400 |
| 400~600 |
| 520~800 |

MC-500a, 630a, 800a